

29	14	(asynchronous\$2 near3 latch\$3) & ((float\$) near10 (detect\$ sense\$1 sensing))	USPAT; US-FGPUB; EPO: JPO; DERWENT; 18k_IDB	2004/04/08 09:53
-	2	"20030051085" .pn.	USPAT; US-FGPUB; EPO: JPO; DERWENT; 18k_IDB	2004/04/07 17:48
-	129	cable near3 ide	USPAT; US-FGPUB; EPO: JPO; DERWENT; 18k_IDB	2004/04/07 17:48
-	15953	latch\$3 near3 (sense senses sensing detect\$3)	USPAT; US-FGPUB; EPO: JPO; DERWENT; 18k_IDB	2004/04/07 18:16
-	3	(latch\$3 near3 (sense senses sensing detect\$3)) & (cable near3 ide)	USPAT; US-FGPUB; EPO: JPO; DERWENT; 18k_IDB	2004/04/07 17:53
-	83	(40pin "40-pin" "40 pin") near3 cable\$1	USPAT; US-FGPUB; EPO: JPO; DERWENT; 18k_IDB	2004/04/07 17:54
-	1	((latch\$3 near3 (sense senses sensing detect\$3)) & (cable near3 ide)) & ((40pin "40-pin" "40 pin") near3 cable\$1)	USPAT; US-FGPUB; EPO: JPO; DERWENT; 18k_IDB	2004/04/07 17:54
-	20	((40pin "40-pin" "40 pin") near3 cable\$1) & (cable near3 ide)	USPAT; US-FGPUB; EPO: JPO; DERWENT; 18k_IDB	2004/04/07 17:54
-	3933	(40pin "40-pin" "40 pin")	USPAT; US-FGPUB; EPO: JPO; DERWENT; 18k_IDB	2004/04/07 17:54
-	1624	(80pin "80-pin" "80 pin" (pin\$1 near2 6467002.PN.))	USPAT; US-FGPUB; EPO: JPO; DERWENT; 18k_IDB	2004/04/07 17:55
-	84	((40pin "40-pin" "40 pin")) & ((80pin "80-pin" "80 pin" (pin\$1 near2 6467002.PN.))	USPAT; US-FGPUB; EPO: JPO; DERWENT; 18k_IDB	2004/04/07 17:55
-	1	((40pin "40-pin" "40 pin")) & ((80pin "80-pin" "80 pin" (pin\$1 near2 6467002.PN.)) & (cable near3 ide)	USPAT; US-FGPUB; EPO: JPO; DERWENT; 18k_IDB	2004/04/07 17:55
-	6	((40pin "40-pin" "40 pin")) & ((80pin "80-pin" "80 pin" (pin\$1 near2 6467002.PN.)) & ide	USPAT; US-FGPUB; EPO: JPO; DERWENT; 18k_IDB	2004/04/07 17:57
-	7	((40pin "40-pin" "40 pin")) & ((80pin "80-pin" "80 pin" (pin\$1 near2 6467002.PN.)) & ata	USPAT; US-FGPUB; EPO: JPO; DERWENT; 18k_IDB	2004/04/07 18:05

220	ground adj1 signal adj1 ground	USPRT; US-PCRB; EPO: JPO; DERMENT; TBM TDB	2004/04/07 18:45
67	cable & (ground adj1 signal adj1 ground)	USPRT; US-PCRB; EPO: JPO; DERMENT; TBM TDB	2004/04/07 18:06
2	ata & (cable & (ground adj1 signal adj1 ground))	USPRT; US-PCRB; EPO: JPO; DERMENT; TBM TDB	2004/04/07 18:06
10	clock#3 & (cable & (ground adj1 signal adj1 ground))	USPRT; US-PCRB; EPO: JPO; DERMENT; TBM TDB	2004/04/07 18:14
122	439/928.1.ccls.	USPRT; US-PCRB; EPO: JPO; DERMENT; TBM TDB	2004/04/07 18:14
11	ide & 439/928.1.ccls.	USPRT; US-PCRB; EPO: JPO; DERMENT; TBM TDB	2004/04/07 18:14
0	(latch#3 near3 (sense senses sensing detect#3)) & 439/928.1.ccls.	USPRT; US-PCRB; EPO: JPO; DERMENT; TBM TDB	2004/04/07 18:15
0	(latch#3 near3 (sense senses sensing detect#3)) & ((latch#3 near3 (sense senses sensing detect#3)) & 439/928.1.ccls.)	USPRT; US-PCRB; EPO: JPO; DERMENT; TBM TDB	2004/04/07 18:15
27	439/928.1.ccls. & (sense senses sensing detect#3)	USPRT; US-PCRB; EPO: JPO; DERMENT; TBM TDB	2004/04/07 18:16
21735	cable near5 (sense senses sensing detect#3)	USPRT; US-PCRB; EPO: JPO; DERMENT; TBM TDB	2004/04/07 18:44
7	(ground adj1 signal adj1 ground) & (cable near5 (sense senses sensing detect#3))	USPRT; US-PCRB; EPO: JPO; DERMENT; TBM TDB	2004/04/07 18:44
37	ground near1 signal near5 ribbon	USPRT; US-PCRB; EPO: JPO; DERMENT; TBM TDB	2004/04/07 18:46
0	(ground near1 signal near5 ribbon) & (latch#3 near3 (sense senses sensing detect#3))	USPRT; US-PCRB; EPO: JPO; DERMENT; TBM TDB	2004/04/07 18:46
3	(ground near1 signal near5 ribbon) & (cable near5 (sense senses sensing detect#3))	USPRT; US-PCRB; EPO: JPO; DERMENT; TBM TDB	2004/04/07 18:51

-	41232	ground near3 (wire\$1 conductor\$1)	USPAT; US-PCPUB; EPO; JFO; DERWENT; IBM_TDB	2004/04/07 18:51
-	24101	(ribbon flat) near3 cable\$1	USPAT; IBM_TDB US-PCPUB; EPO; JFO; DERWENT; IBM_TDB	2004/04/07 20:05
-	1108	(ground near3 (wire\$1 conductor\$1)) & ((ribbon flat) near3 cable\$1)	USPAT; IBM_TDB US-PCPUB; EPO; JFO; DERWENT; IBM_TDB	2004/04/07 18:52
-	59	(cable near5 (sense senses sensing detect\$3)) & ((ground near3 (wire\$1 conductor\$1)) & ((ribbon flat) near3 cable\$1))	USPAT; IBM_TDB US-PCPUB; EPO; JFO; DERWENT; IBM_TDB	2004/04/07 18:55
-	396	324/66.ccls.	USPAT; US-PCPUB; EPO; JFO; DERWENT; IBM_TDB	2004/04/07 18:56
-	14	((ribbon flat) near3 cable\$1) & 324/66.ccls.	USPAT; IBM_TDB US-PCPUB; EPO; JFO; DERWENT; IBM_TDB	2004/04/07 18:59
-	0	(ground adj1 signal adj1 ground) & 324/66.ccls.	USPAT; US-PCPUB; EPO; JFO; DERWENT; IBM_TDB	2004/04/07 18:59
-	51	(ground near3 (wire\$1 conductor\$1)) & 324/66.ccls.	USPAT; IBM_TDB US-PCPUB; EPO; JFO; DERWENT; IBM_TDB	2004/04/07 20:04
-	108	floating near5 latched	USPAT; US-PCPUB; EPO; JFO; DERWENT; IBM_TDB	2004/04/07 20:05
-	2	((ribbon flat) near3 cable\$1) & (floating near5 latched)	USPAT; IBM_TDB US-PCPUB; EPO; JFO; DERWENT; IBM_TDB	2004/04/07 20:05
-	761	floating near5 latch\$2	USPAT; IBM_TDB US-PCPUB; EPO; JFO; DERWENT; IBM_TDB	2004/04/07 20:06
-	1	(cable near5 (sense senses sensing detect\$3)) & (floating near5 latch\$2)	USPAT; IBM_TDB US-PCPUB; EPO; JFO; DERWENT; IBM_TDB	2004/04/07 20:06
-	58	floating near3 (conductor\$1 wire\$1) near5 (detect\$3 sense senses sensing)	USPAT; IBM_TDB US-PCPUB; EPO; JFO; DERWENT; IBM_TDB	2004/04/07 20:08
-	3	cable & (floating near3 (conductor\$1 wire\$1) near5 (detect\$3 sense senses sensing))	USPAT; IBM_TDB US-PCPUB; EPO; JFO; DERWENT; IBM_TDB	2004/04/07 20:09

-	25	ata & pdiag	USPAT; US-PCPUB; EPO; JFO; DERWENT; IBM_TDB	2004/04/07 20:10
-	4	ata & pdiag & cbiid	USPAT; IBM_TDB US-PCPUB; EPO; JFO; DERWENT; IBM_TDB	2004/04/08 06:26

Web Results 1 - 10 of about 609 for floating triggers clock latch asynchronous. (0.14 seconds)

PDF FLASH MEMORY OneNAND 256 / OneNAND 512
OneNAND MCP SPECIFICATION

File Format: PDF/Adobe Acrobat - View as HTML
... During asynchronous read operation, all addresses are transparent
during AVD ... read operation, all addresses are latched on CLK ... AVD is
held low for one clock cycle ...
www.samsung.com/products/Semiconductor/Flash/EagleMCP/
512Mbit/KEC0C0C0C0M/onenand_LIGHT.PDF - Similar pages

PDF EXPERIMENT 6: FLIP-FLOPS AND FEEDBACK
DEVICES

File Format: PDF/Adobe Acrobat - View as HTML
... contact) provides the circuit with floating inputs ... The input change
alone triggers the subsequent output ... the memory element outputs are
synchronized by a clock. ...
www.ece.umn.edu/class/ee2301/lab/EE2301Exp0F03.pdf - Similar pages

PDF IC Implementation and Analysis of Berkele's Single-
Track...

File Format: PDF/Adobe Acrobat - View as HTML
... and so the maximum allowable clock frequency is ... control circuit to
eliminate the floating-node conditions ... Overlap realization use Schmidt
Triggers to develop ...
www.macs.ece.mcgill.ca/~radu/304-522/Projects/ChanProj.pdf -
Similar pages

PDF CA-BIST for Asynchronous Circuits: A Case Study on
the RAPPID...

File Format: PDF/Adobe Acrobat - View as HTML
... All three examples implement a set-reset latch with data ... The down-transition on z
triggers two self-resetting ... CATPG Control 11-cell D1*CA Clock invert/as_is ...
www.cs.utah.edu/classes/cs5830/papers/00836798.pdf - Similar pages

PDF University of Waterloo

File Format: PDF/Adobe Acrobat - View as HTML
... be held stable after the clock edge that triggers the transfer. ... on Read Clock Rate
Limits on Write Clock Rate 1999 ... and (perhaps) Setup Skew and Setup (Latch on D ...
www.pads.uwaterloo.ca/Wayne.Loucks/Teaching/ece324/w1999/s13-two.pdf -
Similar pages

PDF 05-DSP PCI cPCI.p65

File Format: PDF/Adobe Acrobat - View as HTML
... up to four unique timing signals and event triggers to be ... DSP (fixed-point) or 160
MHz TMS320C6701 DSP (floating-point) Two ... I/O 16-bit I/O FIFO Port Clock to 200 ...
www.innovative-dsp.com/support/datasheets/m6x.pdf - Similar pages

CONTROLS CAMAC 145 VACUUM READBACK INTERFACE

... the low to high transition of the signal triggers the flip ... 5.5 The MC68881 Floating
Point Coprocessor (FPC). ... the 10 MHz carrier of the Tevatron clock is detected ...

www.bd.fnrl.gov/controls/camac_modules/c145.htm - 39k - Cached - Similar pages

PDF 32 BIT TRANSPUTER WITH FLOATING POINT UNIT - EXTENDED TEMPERATURE...

File Format: PDF/Adobe Acrobat - View as HTML
... Table 3.2 Typical floating point operation times for ... Select1 ProcSpeed- Select0
Processor Clock Speed Mhz ... Reset initialises the transputer, triggers the memory ...
www.classiccmp.org/transputer/documentation/fmos4258.pdf - Similar pages

CIS 356 Computer Architecture

... flop sample its inputs when the clock signal goes ... Schmitt-triggers are used when
signal levels are ... Floating signals can cause unpredictable behaviour in your ...
nostrab2.polsdam.edu/CIS356/lab5.html - 6k - Cached - Similar pages

Product Folder : SN74LV161A - 4-Bit Synchronous Binary Counters

... A buffered clock (CLK) input triggers the four flip ... These counters feature a fully
independent clock circuit. ... Implications of Slow or Floating CMOS inputs (Rev. ...
focus.ti.com/docs/prod/folders/print/sn74lv161a.html - 83k - Cached - Similar pages

Google

Result Page: 1 2 3 4 5 6 7 8 9 10 Next

floating triggers clock latch async Search

Search within results | Language Tools | Search Tips | Dissatisfied? Help us improve

Google Home - Advertising Products - Business Solutions - About Google

©2004 Google

Web

Results 1 - 10 of about 431 for "cable detect" ata (0.34 seconds)

Ultra ATA/66 FAQ

... The 40-pin, 80-conductor cables support the Cable Detect feature ... Although an Ultra ATA/66 device should work fine in either the black or the gray connector, if ... www.seagate.com/support/kb/disc/ultra_ata_66.html - 31k - Cached - Similar pages

Intel(R) Desktop Board SU810 - Ultra ATA/66 Support

... It is recommended that the Ultra ATA/66 drives be attached to the primary IDE ... Some UDMA cables use a hole in the ribbon cable as a cable detect mechanism to ... support.intel.com/support/motherboards/desktop/SU810/ata66.htm - 23k - Cached - Similar pages

FAQ - ATA 66

... Go to Top: Why is there a blue, a black, and a gray connector on my Ultra ATA/66 cable? The 40-pin, 80-conductor cables support the Cable Detect feature. ... www.directron.com/faqata66.html - 50k - Cached - Similar pages

PCI Automation ATA/ 100 HOT SWAP Hard disk Carrier for 6U...

... to four IDE/ATA devices; 128 Bytes buffer; Supports ultra and multiword DMA timing modes; CRC (Cyclical Redundancy Check); Built in 80-Pin cable detect circuitry; ... www.pcisystems.com/pci-ultra-ata.html - 22k - Cached - Similar pages

Electronic Design: Cable Assemblies And Connectors

Support Ultra ... offer improved data reliability and signal integrity as specified by the Ultra ATA/100 standard, which features built-in 80-conductor cable-detect circuitry. ... www.findarticles.com/cd_dism3161/18_4865353155/p1/article.jhtml - 11k - Cached - Similar pages

HPT370 UDMA/ATA 100 RAID

... One independent IDE channel, supports 40-pin, 80-wire conductor cable; Built in 80-pin cable detect circuitry; 256 Bytes FIFO per ATA channel; Provide PCI power ... www.highpoint-tech.com/hpt371.htm - 9k - Cached - Similar pages

Outpost.com: LATA RAID

... Compliant with UDMA6 ATA/133 Specification; Compliant with ATA/ATAPI-6 Specification; ... Built in 80-pin cable detect circuitry; Supports RAID function 0, 1 and 0+1; ... www.outpost.com/product/3664947 - 25k - Cached - Similar pages

Syba SD-SIL680-RAID Ultra ATA 100/133 IDE RAID PCI Controller Card

... ATA/100, Ultra ATA/66, Ultra ATA/33, EIDE/Fast ATA-2, IDE ... CRC (Cyclical Redundancy Check) protection and verification - Built in 80-pin cable detect circuitry. ...

www.dealsonic.com/sylulata133id.html - 26k - Cached - Similar pages

SYBA SI0680 Ultra ATA 100/133 PCI to ATA IDE RAID Controller ... ATA 33/66/100/133; 48-bit sector addressing; Dual independent DMA channels with 256K FIFO ... 80-pin cable detect. Transfer Rates: PIO-0, 1, 2, 3, 4; MDMA Mode 0, 1, 2, ... www.pcpartscollection.com/sybsylulata1.html - 19k - Cached - Similar pages

Linux-Kernel Archive: Generic ATA-66 Support coming soon. ... dev 01 SIS5513: not 100% native mode: will probe irq's later SIS5513: Chipset Core ATA-66, SIS620 SIS5513: Primary ATA-66, Secondary ATA-33 Cable Detect id60: BM ... www.uwsg.iu.edu/hypermail/linux/kernel/9907.1/0350.html - 4k - Cached - Similar pages

Result Page: 1 2 3 4 5 6 7 8 9 10 Next

"cable detect" ata Search

Search within results | Language Tools | Search Tips | Dissatisfied? Help us Improve

Google Home - Advertising Products - Business Solutions - About Google

©2004 Google

Google

Result Page: 1 2 3 4 5 6 7 8 9 10

data 40 80 detect Search within results | Language Tools | Search Tips | Dissatisfied? Help us improve

Google Home - Advertising Products - Business Solutions - About Google

©2004 Google
products - [Business Solutions](#) - [About Google](#)

The Hardware Site. What is Ultra ATA/66 ?
... 66, the chipset pin count remains the same at 40, ... such that the PC and the Ultra ATA/66 compliant ... both detect the presence of the required 80-conductor cable. ...
www.hardwarepage.nl/ultra66.html - 7k - Cached - Similar pages

Redneck-Puters: Your source for Windows and computer help ...
 ... Can I run UDMA/100 on a 40 pin 40 conductor cable ... 100 will not be enabled unless the
 80-conductor cable ... does not know the difference between Ultra ATA/33, Ultra ...
www.redneck-puters.com/help/ata.shtml - 43k - Cached - Similar pages

...for Proposal for inclusion of additions to **ATA/TAPI-4** required to ...
 File Format: PDF/Adobe Acrobat - [View as HTML](#)
 ... the revisions necessary to describe a 40- conductor cable ... add the following) 80-conductor
 ATA Cable Assembly ... the presence or absence of an 80-conductor assembly ...
www.t13.org/technical/d97121f0.pdf - Similar pages

[PDF Cable Detection Issues in D1410P1](#)
 File Format: PDF/Acrobat - View as HTML
 ... NOTE - Older devices not in compliance with ATA-3 or ... PDIAG-after command or host
 senses before command, 40-conductor is detected as 80-conductor, causing ...
www.t13.org/technical/c601640.pdf - Similar pages
 [More results from www.t13.org]

Linux-Kernel Archive: Re: UDMA 133 on a 40 pin cable
... For some reason the ATA people couldn't get this ... chipsets where there is a 'cable
detect scratch register', where the BIOS writes the 80/40 pin cable ...
www.uwsg.ii.edu/hypertextmail/linux/ kernel/0301.0/0644.html - 8k - [Cached](#) - [Similar pages](#)

Maxtor DiamondMax 40
... The DiamondMax 40 has capacities up to 40.9 GB ... your BIOS does not utilize Auto-Detect,
... Maxtor recommends ... Cable Requirements: An 80-Wire UDMA interface Cable ...
sunstarco.com/ Hard%20Drive%20Info/Maxtor/Maxtor%20DiamondMax%2040%20Ultra%20DMA%2066.htm - 33k
[Cached](#) - [Similar pages](#)